




Type 1




Type 2




Type 3




Type 4




AP-26




AP-11




Hackberry Spring




Walnut Spring




AP-27




AP-23




AP-05




AP-14




AP-29




DPW-06




AP-22



DPW-01



DPW-02




SAFFORD MINE

2007-2008 3M Evaluation


CLEAR
CREEK
ASSOCIATES

Figure 19. 2005 Well and Spring Stiff Diagrams



Type 1




Type 2




Type 3




Type 4




AP-26




AP-09




Hackberry Spring




Walnut Spring




DPW-06




AP-27




AP-11




AP-05




AP-22




AP-29




AP-23




DPW-01




DPW-02



GI-P1



Bryce Spring



SAFFORD MINE

2007-2008 3M Evaluation

Figure 20. 2007 Well and Spring Stiff Diagrams